






(a) Protruding Dispenser Below Grab Bar



(c) Recessed Dispenser




FIGURE 606.3
HEIGHT OF LAVATORIES AND SINKS




FIGURE 306.2
TOE CLEARANCE




FIGURE 306.3
KNEE CLEARANCE